

Washington Metropolitan Area Transit Commission

2021 Carrier Annual Report Form



Read the accompanying instructions carefully before completing this form.

1. CARRIER INFORMATION:

1765	Holiday Tours, Inc., t/a Holiday			
*WMATC No. *Name of Carrier (as shown on certificate of authority)				
10367 Randleman Road		Randleman	NC	27317-8076
*Street Address of Principal Place of Business		Apt./Suite	City	State
Mailing Address (if different from street address)		Apt./Suite	City	State
(336) 498-9000	3984 (336) 823-3983	496-0660 (336) 498-2616	Bethel	nickr@tustholiday.com
*Telephone	Other Telephone	Fax	E-mail	

2. OTHER PASSENGER CARRIER AUTHORITY (if applicable, list carrier/permit number):

252234			
USDOT No.	DC DFHV No.	Virginia DMV passenger carrier No.	Maryland PSC No.

3. CARRIER CONTACT PERSON (at mailing address to whom we should direct inquiries):

Mr. Nick Roberts	Beth Lyon	Safety Director	
*Name		*Title	
(336) 498-9000	3984 (336) 823-3983	496-0660 (336) 498-2616	bethl@trustholiday.com nickr@tustholiday.com
*Telephone	Other Telephone	Fax	E-mail

4. REGISTERED AGENT INSIDE THE METROPOLITAN DISTRICT FOR SERVICE OF PROCESS *Complete section 4 only if the principal place of business in section 1 is outside the Metropolitan District. The Metropolitan District includes the District of Columbia, Prince George's Co., Montgomery Co., Alexandria, Arlington, Fairfax, Falls Church, and Dulles Airport. For a full description, see www.wmatc.gov.

Ken Presley	(800) 424-8262	kpresley@uma.org	
Name of Registered Agent for Service of Process		Telephone	E-mail
113 S. West Street, 4th Floor		Alexandria	VA
Agent Address (must be inside Metropolitan District)	Apt./Suite	City	State
			22314-2851
			Zip

Fleet #	Model	Year	Make	VIN	License Plate	State Registered	Capacity	Wheelchair Lift
137	Prevost	2000	H3-45	2PCH33498Y1013762	LA20704	NC	54	N
138	Prevost	2000	H3-45	2PCH33499Y1013768	LA20705	NC	54	N
139	Prevost	2001	H3-45	2PCH3349711014214	LA20706	NC	54	N
140	Prevost	2001	H3-45	2PCH3349011014216	LA20707	NC	54	N
141	Prevost	2001	H3-45	2PCH3349411014218	LA20708	NC	54	N
142	Prevost	2001	H3-45	2PCH3349611014219	LA20709	NC	54	N
143	Prevost	2001	H3-45	2PCH3349411014221	LA20710	NC	54	N
144	Prevost	2001	H3-45	2PCH3349811014223	LA20711	NC	54	N
217	Prevost	2008	H3-45	2PCH334978C711199	LA20726	NC	56	N
219	Prevost	2009	H3-45	2PCH334919C711457	LA20728	NC	56	N
220	Prevost	2012	H3-45	2PCH33496CC712000	LA20729	NC	56	N
221	Prevost	2012	H3-45	2PCH3349XCC712002	LA20730	NC	56	N
222	Prevost	2013	H3-45	2PCH33490DC712320	LA20771	NC	56	N
223	Prevost	2014	H3-45	2PCH3349XEC712598	LA20731	NC	56	N
224	Prevost	2014	H3-45	2PCH33494EC712600	LA20732	NC	56	N
225	Prevost	2015	H3-45	2PCH33490FC712918	LA20733	NC	56	N
226	Prevost	2015	H3-45	2PCH33499FC712920	LA20734	NC	56	N
227	Prevost	2016	H3-45	2PCH33495GC713242	LA20735	NC	56	N
228	Prevost	2016	H3-45	2PCH33490GC713245	LA20736	NC	56	N
231	Prevost	2017	H3-45	2PCH33492HC713684	LA20772	NC	56	N
232	Prevost	2017	H3-45	2PCH33494HC713685	LA20739	NC	56	N
233	Prevost	2017	H3-45	2PCH33496HC713686	LA20740	NC	56	N
234	Prevost	2018	H3-45	2PCH33497JC710169	LA20773	NC	56	N
235	Prevost	2018	H3-45	2PCH33493JC710170	LA20741	NC	56	N
236	Prevost	2019	H3-45	2PCH33499KC720574	LA13993	NC	56	N
237	Prevost	2020	H3-45	2PCH33490LC720996	LA13998	NC	56	N
238	Prevost	2020	H3-45	2PCH33494LC720998	LA13999	NC	56	N
239	Prevost	2020	H3-45	2PCH33490LC721002	LA14000	NC	56	N
240	Prevost	2020	H3-45	2PCH33494LC721004	LA12750	NC	56	N
409	Prevost	2007	H3-45	2PCH3349571710837	LA20750	NC	50	N
410	Prevost	2009	H3-45	2PCH334969C711454	LA20751	NC	50	N
411	Prevost	2015	H3-45	2PCH33490FC712921	LA20752	NC	52	N
412	Prevost	2016	H3-45	2PCH33492GC713246	LA20753	NC	50	N
414	Prevost	2017	H3-45	2PCH3349XHC713688	LA20754	NC	50	N
415	Prevost	2018	H3-45	2PCH33495JC710168	LA20755	NC	50	N
416	Prevost	2018	H3-45	2PCH33495JC710171	LA20756	NC	50	N
417	Prevost	2020	H3-45	2PCH33497LC721000	LA12751	NC	50	N
512	Prevost	2014	H3-45	2PCH33498EC712597	LA20762	NC	52	Y
514	Prevost	2019	H3-45	2PCH33492KC720576	LA13994	NC	50	Y
604	Temsa	2015	TS35	NLTRPPU73F1000321	LA20766	NC	38	N
605	Temsa	2017	TS-35	NLTRPPY72H1000453	LA20767	NC	38	N
907	Temsa	2015	TS-30	NLTAPLU56F1000155	LA20768	NC	30	N
908	Temsa	2015	TS-30	NLTAPLU55F1000163	LA20769	NC	30	N